



HERITAGE THERMAL SERVICES
1250 St. George Street
East Liverpool, Ohio 43920-3400
Phone: 330-385-7337
Fax: 330-385-7813
www.heritage-thermal.com

OHSAS 18001: 2007
ISO 14001: 2004
ISO 9001: 2008

February 27, 2013
VIA UPS

Mr. George Czerniak, Chief
U.S. EPA Region V
Air Enforcement and Compliance Assurance
Branch
Mail Code AE-17J
77 West Jackson
Chicago, IL 60604

Mr. Erik Bewley
OEPA-DAPC-NEDO
Environmental Specialist
2110 E. Aurora Road
Twinsburg, OH 44087

RE: HERITAGE-WTI, INC.
d/b/a HERITAGE THERMAL SERVICES
EXCESSIVE EXCEEDANCE REPORTING

Dear Mr. Czerniak:

Please find enclosed a written report entitled MACT Excessive Exceedance Report for Heritage-WTI, Inc. This report is required by 40 CFR 63.1206 (c)(3)(vi) whenever there is more than ten emission standard or operating parameter exceedances that occur within a sixty-day period.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are certain penalties for submitting false information including the possibility of fine and imprisonment for knowing violations.

Thank you and if you have any questions or comments, please call me at the above number.

Sincerely,

A handwritten signature in black ink, appearing to read "Stewart Fletcher".

Stewart Fletcher
General Manager
Heritage Thermal Services

cc: Ed Fasco, Ohio EPA-DAPC-NEDO



Recycled Paper

MACT EXCESSIVE EXCEEDANCE REPORT

Heritage-WTI, Inc

February 27, 2013

Events

#	Name	Start Time	End Time	Cause (Report)	Cause Description	Corrective Actions	(hr)	(min)	(sec)
1	SCC Temperature	12/27/2012 9:38:40 AM	12/27/2012 9:55:42 AM	Operator Error- Poor Operation	Operator failed to maintain SCC temperature.	Increased burner. Restarted unit.	0	17	02
2	THC	1/19/2013 9:46:01 PM	1/19/2013 10:42:49 PM	Operator Error - Feed Prep	Improperly prepared waste caused poor combustion.	Restarted unit. Reaffirmed prep.	0	56	48
3	THC	1/23/2013 3:58:32 PM	1/23/2013 5:04:40 PM	Operator Error - Feed Prep	Improperly prepared waste cause poor combustion.	Restarted unit. Revised processing.	1	6	8
4	SCC Pressure Using Seals	2/1/2013 6:14:13 PM	2/1/2013 6:14:49 PM	Operator Error - Feed Prep	Improperly prepared waste caused pressure spike.	Restarted unit. Removed from waste mix.	0	0	36
5	THC	2/5/2013 9:10:17 PM	2/5/2013 10:10:10 PM	Operator Error - Feed Prep	Improperly prepared waste caused poor combustion.	Restarted unit. Removed from waste mix.	0	59	53
6	THC	2/14/2013 7:06:56 AM	2/14/2013 8:04:37 AM	Operator Error - Feed Prep	Improperly prepared waste caused poor combustion.	Restarted unit. Revised procedure.	0	57	41
7	THC	2/17/2013 1:13:43 AM	2/17/2013 2:13:39 AM	Operator Error - Feed Prep	Improperly prepared waste caused poor combustion.	Restarted unit. Removed from waste mix.	0	59	56
8	THC	2/19/2013 9:15:18 AM	2/19/2013 9:42:19 AM	Operator Error - Feed Prep	Improperly prepared waste caused poor combustion.	Restarted unit. Removed from waste mix.	0	27	1
9	THC	2/20/2013 9:29:28 AM	2/20/2013 10:29:33 AM	Operator Error - Feed Prep	Improperly prepared waste caused poor combustion.	Restarted unit. Removed from waste mix.	1	0	5
10	THC	2/24/2013 8:46:09 AM	2/24/2013 9:43:00 AM	Operator Error - Poor Operation	Operator failed to adjust to adverse kiln conditions leading to poor combustion.	Restarted unit. Reduced feeds.	0	56	51

** End of report **

bcc: Env. Dept
Bob Buchheit
Kevin Lloyd

file name: environ/MACT/HWC MACT/exceedances/eer13_0227